

Duquesne Light Company

Beaver Valley Power Station
P.O. Box 4
Shippingport, PA 15077-0004
(412) 393-5206
(412) 643-8069 FAX

GEORGE S. THOMAS
Division Vice President
Nuclear Services
Nuclear Power Division

May 19, 1995


U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555-0001

Subject: Beaver Valley Power Station, Unit No. 1 and No. 2
BV-1 Docket No. 50-334, License No. DPR-66
BV-2 Docket No. 50-412, License No. NPF-73
Resolution of Generic Letter 93-04, "Rod Control System Failure and
Withdrawal of Rod Control Cluster Assemblies, 10 CFR 50.54(f)"
(TAC Nos. M86831 and M86832)

By letter dated January 6, 1995, Duquesne Light Company (DLC) committed to make the current order timing modifications to the Rod Control System detailed in Westinghouse Technical Bulletin NSD-TB-94-05-R0 at Beaver Valley Unit No. 1 during its tenth refueling outage and at Beaver Valley Unit No. 2 during its fifth refueling outage. DLC also committed to perform new current order surveillance tests which were recommended by the Westinghouse Owner's Group at the end of the refueling outage of each unit. These activities have been completed for Beaver Valley Units No. 1 and No. 2. These actions complete the activities necessary for the resolution of Generic Letter 93-04 for Beaver Valley Units No. 1 and No. 2.

If you have any questions concerning the above actions, please contact N. R. Tonet, Manager, Nuclear Safety Department at (412) 393-5210.

Sincerely,


George S. Thomas

c: Mr. L. W. Rossbach, Sr. Resident Inspector
Mr. T. T. Martin, NRC Region I Administrator
Mr. D. S. Brinkman, Sr. Project Manager

9505310062 950519
PDR ADDCK 05000334
P PDR

A030
1/0