



File
Telegram

NK8545(1806)(2-180130E152)PD 06/01/73 1804

ICS IPMMTZZ CSF

2124504673 TDMT NEW YORK NY 180 06-C: 0604P EST

PMS JAMES P O'REILLY, DLR

DIRECTOR REGULATORY OPERATIONS REGION 1 US ATOMIC ENERGY COMMISSION

970 BROAD ST

NEWARK NJ 07102

RE TO INDIAN POINT UNIT NUMBER 2 AEC DOCKET NUMBER 50-247 FACILITY
OPERATING LICENSE DPR-26 DEAR MR O'REILLY IN ACCORDANCE WITH
THE REQUIREMENTS OF TECHNICAL SPECIFICATION 6.6.1.B WE WISH
TO INFORM YOU OF AN ABNORMAL OCCURANCE (A03-2-7) WHICH TOOK
PLACE ON JUNE 1 1973 AT 02:02 HOURS. DURING THE COURSE OF 0
POWER LEVEL TESTING ON THIS DATE, A SPURIOUS SAFETY INJECTION
SIGNAL WAS INITIATED. THE THREE SAFETY INJECTION (HIGH HEAD)
PUMPS STARTED AUTOMATICALLY AS REQUIRED BY THIS SIGNAL, HOWEVER,
ONE OF THE TWO VALVES (VALVE 851A) TYING THE DISCHARGES OF THE

BF-1201 (RS-69)



Telegram

PUMPS TOGETHER WAS DRIVEN TO ITS CLOSED POSITION. IN ACCORDANCE
WITH THE REQUIREMENTS OF TECHNICAL SPECIFICATION 6.2, NOTIFICATION
OF THE CHAIRMAN OF THE NUCLEAR FACILITIES SAFETY COMMITTEE HAS
TAKEN PLACE MR A FASANO OF YOUR OFFICE WAS ALSO NOTIFIED BY
TELEPHONE ON JUNE 1 1973 OF THE OCCURANCE BY MR J M MAKEPEACE,
CHIEF ENGINEER UNIT NUMBER 2. WE ARE CURRENTLY INVESTIGATING
THE CAUSE OF THE VALVE ACTUATION AND THE RESULTS OF ANY CORRECTIVE
ACTIONS WILL BE SUBMITTED IN THE REQUIRED 10 DAY REPORT. VERY
TRULY YOURS

WILLIAM E CALDWELL JR VICE PRESIDENT CONSOLIDATED EDISON CO
OF NEW YORK INC

8304060081 730611
PDR ADOCK 05000247
S PDR

Handwritten: 47
50-2