

LICENSEE EVENT REPORT

CONTROL BLOCK:

1					6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE			
01	N	Y	N	M	P	1						-								4	1	1	1	1		0	3	
7	8	9				14	15										25			26				30			31	32

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE						REPORT DATE							
01		-	-	L	L	0	5	0	-	0	2	2	0	1	0	2	5	7	6	0	3	1	4	7	7
7	8	57	58	59	60	61							68	69						75					80

EVENT	DESCRIPTION
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

02	No. 12 Feedwater Pump, one of two redundant pumps for the HPCI System, was taken out	80
03	of service for repair of sealwater strainer and small gear box leaks. No. 11	80
04	Feedwater Pump, the redundant pump, was operable and operating during maintenance	80
05	on No. 12 pump.	80
06	LER 76-43	80

SYSTEM CODE CAUSE CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION
 [07] [C] [H] [F] [Z] [Z] [9] [9] [9] [N]
 7 8 9 10 11 12 13 14 15 16 17 43 44 45 46 47 48

CAUSE DESCRIPTION

08	One of a redundant component was taken out of service to perform maintenance while	80
09	unit was on load.	80
10		80

11	FACILITY STATUS [E]	% POWER [0][7][8]	OTHER STATUS NA	METHOD OF DISCOVERY [C]	DISCOVERY DESCRIPTION NA
7 8	9	10 11 12	13	44 45	30
12	FORM OF ACTIVITY RELEASED [Z]	CONTENT OF RELEASE [Z]	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA	
7 8	9	10 11	44	45	80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	Z	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

~~DATA~~ CONSEQUENCES PROBABLE

15 NA 7 8 9 80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	5	2	NA

7 8 9 PUBLICITY NA 8304060410 770314 PDR ADOCK 05000220 S PDR

ADDITIONAL FACTORS

13 Timely report not made since event was not recognized as reportable occurrence at the
7 B 9 83

time.

13
7 B 9 83

NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N. Y. 13202

March 14, 1977



Mr. James P. O'Reilly
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

Licensee Event Reports, 76-43 and 76-44, are hereby submitted in the format designated in the Booklet 00E-SS-001 as revised December 8, 1975. These reports were not submitted within 30 days of the event, since the occurrence was not recognized as reportable at that time.

Very truly yours,

R.R. Schneider
R.R. Schneider
Vice President -
Electric Production

MAS/mtm

Attachments

CERTIFIED - RETURN RECEIPT REQUEST

770870104

~~3-23-77~~