

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE		
01	N	Y	N	M	P	1						-								4	1	1	1	1		0	3
7	8	9				14	15											25		26					30	31	32

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE								
01		M	I	L	L	0	5	0	-	0	2	2	0		1	2	2	2	7	6		0	1	8	7	7
7	8	57	58	59	60	51								68	69						74	75				80

EVENT	DESCRIPTION
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

02	Reactor Building Integrity disrupted momentarily when both air lock doors were										80					
03	opened together. There was no significant effect since a negative pressure										80					
04	existed in the building, preventing any release of radioactive gases to the										80					
05	atmosphere.										80					
06	LER 76-42										80					
SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION											80					
07	Z	Z	D	Z	Z	Z	Z	Z	Z	Z	9	9	9	N		
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

CAUSE DESCRIPTION

03	Two doors were opened simultaneously in the Reactor Building Extension air lock															80
09	Standing Order NMPSO #12 was issued specifying control procedures to follow in															80
10	opening doors.															80
11	Reported by on the job operator															80
12	N/A															80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	Z	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	N/A

~~000000~~ CONSEQUENCES Probable

15 | No effect to public or personnel on job or plant operation.

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	5	2	N/A

PUBLICITY

17 None PDR ADUCK 05000220
7 8 9 S PDR

ADDITIONAL FACTORS

13 Interlock lights were being installed at the time of the event. These will replace
7 8 9 a tagging procedure then in use. 80

IE FILE COPY

NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

January 19, 1977

Mr. James P. O'Reilly
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specification 6.9, we hereby submit Licensee Event
Reports 76-42 and 77-01.

These reports were completed within the intent of the Licensee
Event Report Instruction Booklet 00E-SS-001, dated October 1974,
revised December 24, 1974.

Sincerely yours,

R.R. Schneider
R.R. Schneider
Vice President -
Electric Production

mtm

Enc.



1004