

CONTROL BLOCK:

1					6

LICENSEE
NAME

LICENSE NUMBER

LICENSE
TYPE

EVENT
TYPE

01		N	Y	N	M	P	1
7	8						14

LICENSE NUMBER

15

4 1 1 1 1

EVENT TYPE	
0	3

01	CON'T		
7	8	57	58

REPORT
TYPE
[L]
59

REPORT
SOURCE
[L]
60

DOCKET NUMBER
050-0220

EVENT DATE					
0	9	0	8	7	6

REPORT DATE					
0	9	2	3	7	6

02	During a management review, it was revealed that surveillance required by	
7 8 9		
03	Technical Specifications 4.3.6(a) on vacuum breaker exercising following	80
7 8 9		
04	relief valve discharge to Torus had not been performed following scrams on	80
7 8 9		
05	8-6-76 and 8-23-76.	80
7 8 9		
06		80
7 8 9		
	LER 76-33	
7 8 9		
	SYSTEM - CAUSE	PRIME
7 8 9		

SYSTEM CODE		CAUSE CODE		COMPONENT CODE						FRAME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
0	7	Z	Z	Z	Z	Z	Z	Z	Z	-	Z	9	9	9	-		
7	8	9	10	11	12				17	43	44				47	48	

09	The surveillance requirements were never posted on the Startup Check-off Sheets.	80
09	This has been changed in OP-43 and also on Startup Form ST-M3.	80
10		80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	95	N/A				During a review	
7	8	9	10	11	12	13	14	15	16

		FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	2	3	4	5	6	7	8	9	10
		Z		Z		N/A		N/A	

NUMBER			TYPE	DESCRIPTION
13	0	0	2	N/A

NUMBER			DESCRIPTION
14	0	0	N/A

15 NONE

TYPE		DESCRIPTION
15	Z	N/A

17	None
----	------

13 | None
89

PDR ADDCK 05000220
S PDR

8304060457 760923
PDR ADOCK 05000220
S PDR

13

NAME: _____ PHONE: _____