

LICENSEE EVENT REPORT

CONTROL BLOCK:

1					6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE							
0	1	N	Y	N	M	F	1			-					-			4	1	1	1	1	0	1
7	8	9					14	15								25	26					30	31	32

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE																		
0	1	M	I	L	L	0	5	0	—	0	2	2	0	0	8	0	9	7	6	0	9	0	1	7	6							
7	8	57	58	59	60	61							68	69										74	75							80

[illegible]

02	During a routine reactor startup, #11 Feedwater pump failed to start when manually	80
03	initiated. #11 FW pump is one of two pumps required for HPCI. #12 FW pump,	80
04	the redundant component, was started successfully, therefore no hazard	80
05	was presented to the general public.	80
06		80

LER 76-31

SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

07	I	B	E	I	N	S	T	R	U	N	A	1	0	9	-
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

03	An Agastat time delay relay model #2462 PD Serial #2683521, 120 V DC failed to	
7 8 9		
03	function thus not allowing operation of the pump.	80
7 8 9		
10		80
7 8 9		

11	FACILITY STATUS C	% POWER 077	OTHER STATUS	METHOD OF DISCOVERY a	DISCOVERY DESCRIPTION during plant startup
7 8	9	10 12	13	44 45	46 80
12	FORM OF ACTIVITY RELEASED Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY N/A		LOCATION OF RELEASE
7 8	9	10 11	44	45	80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	2	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION
14	0	0	0	N/A

DEFINITE CONSEQUENCES PROBABLE

1	5	None
---	---	------

7 8 9
10

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	3	2	N/A

PUBLCITY		8304060467 760901	BU
17	None	PDR ADOCK 05000220	
7	8	S PDR	

ADDITIONAL FACTORS

13 | None

19

7 8 9