

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER										LICENSE TYPE					EVENT TYPE			
01	N	Y	R	E	G	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9			14	15										25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER								EVENT DATE					REPORT DATE						
01	CON'T	O	L	0	5	0	-	0	2	4	4	1	2	1	7	7	6	0	5	2	7	7	7
7	8	57	58	59	60	61					68	69				74	75						80

EVENT DESCRIPTION

02	During normal rounds an operator discovered liquid leaking from the "A" mixed bed																							80
03	demineralizer inlet pipe. (Reportable Occurrence 76-30, 30-day).																							80
04																								80
05																								80
06																								80

SYSTEM CODE	CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION				
07	C	G	B	P	I	P	E	X	X	N	B	1	3	0	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Pinhole leak in weld between pipe and elbow. Hole was ground out and repaired using																							80
09	proper welding procedure. The piping was visually inspected for leakage after return																							80
10	to service. CAR 1114 was issued for this event.																							80

FACILITY STATUS	% POWER	OTHER STATUS			METHOD OF DISCOVERY	DISCOVERY DESCRIPTION			
11	E	1	0	0	NA	b	Operator making rounds		
7	8	9	10	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	Z	NA	NA	NA		
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION				
13	0	0	0	Z	NA	
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER	DESCRIPTION				
14	0	0	0	NA	
7	8	9	11	12	80

OFFSITE CONSEQUENCES

15	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION																							
16	Z	NA																					80	
7	8	9	10																					80

PUBLICITY

17	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: Dave Hamelink

PHONE: 716/546-2700, ext. 291-215

8304070049 770527
PDR ADOCK 05000244
S PDR

RECEIVED

NEW YORK STATE

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE JR
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

May 27, 1977

IE FILE COPY

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406



Subject: Supplemental reports on Reportable Occurrences:
76-27 (30-day report) Leak in letdown diversion line
76-30 (30-day report) "A" mixed bed demineralizer inlet
piping leak
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:

The purpose of this letter is to provide you with corrected component manufacturer information in connection with the subject reports which were submitted January 4 and January 12, 1977 respectively. The attached update reports LER 76-27/30 and LER 76-30/30 provide this information.

Two additional copies of this letter and the attachments are enclosed to conform to the original submittal of LER 76-27/3L and LER 76-30/3L.

Very truly yours,

L. D. White, Jr.

L. D. White, Jr.

cc: Dr. Ernst Volgenau (30)
Mr. William G. McDonald (3)

771540052