

LER 76-27/30 Update Report - Previous Report Date 1/4/77
LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 N Y R E G I 14														LICENSE NUMBER 00-000000-00 25												LICENSE TYPE 41111 30					EVENT TYPE 03 32	
01 CONT 7 8		CATEGORY 57 58		REPORT TYPE 59		REPORT SOURCE 60		DOCKET NUMBER 050-0244 68								EVENT DATE 121676 74					REPORT DATE 052777 80											

EVENT DESCRIPTION

02 During normal rounds operator noticed liquid coming through insulation on 2" letdown 80																																																																															
03 diversion line. Upon return to steady state letdown condition, line was isolated. 80																																																																															
04 (Reportable Occurrence 76-27, 30-day). 80																																																																															
05 80																																																																															
06 80																																																																															

SYSTEM CODE 07 C G 7 8 9 10		CAUSE CODE B 11		COMPONENT CODE P I P E X X 17				PRIME COMPONENT SUPPLIER N 43		COMPONENT MANUFACTURER B 1 3 0 47				VIOLATION N 48	
--------------------------------	--	--------------------	--	----------------------------------	--	--	--	----------------------------------	--	--------------------------------------	--	--	--	-------------------	--

CAUSE DESCRIPTION

08 A pinhole leak was found in socket weld between pipe and elbow. Weld was built up 80																																																																															
09 in area of leak, and a visual inspection performed upon return of system to service ver- 80																																																																															
10 ified leak was stopped. This section of line was (cont'd. under Additional Factors) 80																																																																															

FACILITY STATUS 11 E 7 8 9		% POWER 100 12 13		OTHER STATUS NA 44		METHOD OF DISCOVERY b 45		DISCOVERY DESCRIPTION Operator making rounds 80											
FORM OF ACTIVITY RELEASED 12 Z 7 8 9		CONTENT OF RELEASE 2 10 11		AMOUNT OF ACTIVITY NA 44		LOCATION OF RELEASE NA 45		80											

PERSONNEL EXPOSURES

NUMBER 13 000 7 8 9 11		TYPE 2 12		DESCRIPTION NA 13 80															
---------------------------	--	--------------	--	-------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES

NUMBER 14 000 7 8 9 11		DESCRIPTION NA 12 80															
---------------------------	--	-------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

OFFSITE CONSEQUENCES

15 NA 80																																																																															
----------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z 7 8 9 10		DESCRIPTION NA 80															
-----------------------	--	----------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

PUBLICITY

17 NA 7 8 9		8304070085 770527 PDR ADOCK 05000244 S PDR 80															
-------------	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

18 (cont'd. from Cause Description) replaced during refueling shutdown to remove weld 80																																																																															
19 which had been leaking. CAR 1111 was issued to document this corrective action. 80																																																																															

NAME: James Witte/D. Hamelink PHONE: 716/546-2700, ext. 291-215



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE JR.
VICE PRESIDENT

TELEPHONE
AREA CODE TEL. 546-2700

IE FILE COPY

May 27, 1977

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Supplemental reports on Reportable Occurrences:
 (76-27) (30-day report) Leak in letdown diversion line
 76-30 (30-day report) "A" mixed bed demineralizer inlet
 piping leak
 R. E. Ginna Nuclear Power Plant, Unit No. 1
 Docket No. 50-244

Dear Mr. O'Reilly:

The purpose of this letter is to provide you with corrected component manufacturer information in connection with the subject reports which were submitted January 4 and January 12, 1977 respectively. The attached update reports LER 76-27/3O and LER 76-30/3O provide this information.

Two additional copies of this letter and the attachments are enclosed to conform to the original submittal of LER 76-27/3L and LER 76-30/3L.

Very truly yours,

L. D. White, Jr.

cc: Dr. Ernst Volgenau (30)
 Mr. William G. McDonald (3)