

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE
NAME

LICENSE NUMBER

LICENSE
TYPE

EVENT
TYPE

02 During review by contractor's Q.C. personnel of work documentation package, it was
7 8 9 80

03 determined that piping installed in S.I. Test Line during spring 1976 refueling shutdown
7 8 9 80

04 was 3/4" Sch 40 S stainless steel rather than 3/4" Sch 80 S stainless steel specified.
7 8 9 80

05 The PORC has determined that with the Sch 40 pipe section S.I. pumps would have been
7 8 9 80

06 capable of fulfilling their intended function. With unit(cont'd. under Additional Factors)
7 8 9 80

PRIME 80

SYSTEM
CODECAUSE
CODE

COMPONENT CODE

PRIME
COMPONENT
SUPPLIER

COMPONENT
MANUFACTURER

VIOLATION

08 Inadequate administrative controls to assure proper installation of materials. Contractor
7 8 9
09 procedures and plant procedures have been changed to provide more stringent controls
7 8 9
10 for the verification of acceptability of installed modifications prior to plant operation. 80

FACILITY
STATUS

% POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

FORM OF
ACTIVITY
RELEASED

CONTENT

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

| NUMBER | | | TYPE | DESCRIPTION |
|--------|-----|--|------|-------------|
| 13 | 000 | | 2 | NA |

| NUMBER | | | DESCRIPTION |
|--------|---|---|-------------|
| 14 | 0 | 0 | NA |

15 NA

| TYPE | | DESCRIPTION |
|------|---|-------------|
| 16 | 8 | NA |

17 NA S DR ADUCK 05000244 PDR

8304070147 760914
PDR ADOCK 05000244
S PDR

18 (cont'd. from Event Description) shutdown contractor immediately replaced piping with
8 9 correct material. CAR 1098 was issued for this event. (Reportable Occurrence 76-23,
19 30-day). 80

NAME: James Witte PHONE: 716/546-2700, ext. 291-206



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

September 14, 1976

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406



Subject: Reportable Occurrence 76-23 (30-day report), Incorrect piping
installation for modification SM 75-9.21
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly

In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-23, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)
Mr. William G. McDonald (3)

9475

COPY SENT REGION