

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME				LICENSE NUMBER								LICENSE TYPE					EVENT TYPE							
01	N	Y	R	E	G	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9				14	15									25		26					31	32

  

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE									
01	CON'T	L	L	0	5	0	-	0	2	4	4	0	6	1	8	7	6	0	7	1	5	7	6
7	8	57	58	59	60			61					69				74		75				81

EVENT	DESCRIPTION
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

02	During performance of procedure S-16.11, "Monitoring and Enrichment of Accumulator	80
03	Boron Concentration," "A" Accumu drain valve was opened with controls at the rear of	80
04	control board. The operator then proceeded to front of control board to monitor level	80
05	indicators reading more conservative than those at the rear, and noted level lowered to	80
06	46%. "B" Accumulator was at proper level. Proper (cont'd. under Additional Factors)	80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION		
07	S F	D		A	C	C	U	M	U	N	W	1	2	0	Y	
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

## CAUSE DESCRIPTION

08	S-16.11 did not provide precautions relative to operator remaining at valve controls	80
09	during lowering level. As recommended by PORC (meeting 75-76, item 76-932) S-16.11	80
10	was changed to incorporate the appropriate precautions.	80

11	FACILITY STATUS E	% POWER 100	OTHER STATUS NA	METHOD OF DISCOVERY a	DISCOVERY DESCRIPTION NA	80
7 8	9	10 12	13 44	45 46	80	
FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE 2	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA			
12	9	10 11	44 45	80		
7 8						

## PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	Z	NA
8	9	11	12	13

## PERSONNEL INJURIES

NUMBER			DESCRIPTION	
14	0	0	0	NA

## OFFSITE CONSEQUENCES

15	NA
----	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	2	NA

## PUBLICITY

17 NA PDR ADOCK 05000244  
S PDR

### ADDITIONAL FACTORS

19 (cont'd. from Event Description) level was restored in 11 minutes. Corrective Action  
8 9 Report 1081 was issued and documents the PORC-recommended actions. (Reportable  
19 Occurrence 76-17, 30-day). 80

NAME: Bruce A. Snow

PHONE: 716/546-2700, ext. 291-214

REC

FILE COPY

REC  
FILE  
STATE

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700

July 15, 1976

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406



Subject: Reportable Occurrence 76-17 (30-day report), "A" Accumulator  
level below Technical Specification limit  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-17, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

*L. D. White, Jr.*  
L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)  
Mr. William G. McDonald (3)

COPY SENT REGION *[Signature]*

7224