

LICENSEE EVENT REPORT

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 N Y R E G I 14 15														LICENSE NUMBER 0 0 - 0 0 0 0 0 0 - 0 0 25 26										LICENSE TYPE 4 1 1 1 1 30					EVENT TYPE 0 3 31 32	
01 CONT 7 8		CATEGORY 57 58		REPORT TYPE 59 60		REPORT SOURCE 61 62		DOCKET NUMBER 0 5 0 - 0 2 4 4 68 69										EVENT DATE 0 5 2 0 7 6 74 75					REPORT DATE 0 6 0 4 7 6 80							

EVENT DESCRIPTION

02 During check of computer rod position program, rod position deviation channel was found																																																																															
03 to be inoperable. A hand log was started as specified by Tech.Spec. Table 3.5-1, Item																																																																															
04 16a. Item 16b was still in service. Computer technician re-initialized program and rod																																																																															
05 position program check was completed satisfactorily. The channel was deemed operable																																																																															
06 and the hand log terminated. (Reportable Occurrence 50-244/76-16, 30-day).																																																																															

SYSTEM CODE 07 I F 7 8 9 10										CAUSE CODE E 11										COMPONENT CODE I N S T R U 12 13 14 15 16 17										PRIME COMPONENT SUPPLIER N 43										COMPONENT MANUFACTURER W 1 2 0 44 45 46 47										VIOLATION N 48									
--------------------------------	--	--	--	--	--	--	--	--	--	--------------------	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	----------------------------------	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	-------------------	--	--	--	--	--	--	--	--	--

CAUSE DESCRIPTION

08 The event was caused by a failure in the computer to correctly monitor rod position																																																																															
09 deviation. Upon re-initializing, the computer program was again found operable.																																																																															
10 Operator verification of Tech.Spec.-related programs in the (cont'd. on attached sheet)																																																																															

FACILITY STATUS 11 E 7 8 9										% POWER 1 0 0 10 11 12										OTHER STATUS NA 13 14 15 16 17 18 19 20										METHOD OF DISCOVERY b 44 45 46										DISCOVERY DESCRIPTION NA 47 48 49 50									
FORM OF ACTIVITY RELEASED 12 Z 7 8 9										CONTENT OF RELEASE Z 10 11 12										AMOUNT OF ACTIVITY NA 13 14 15 16 17 18 19 20										LOCATION OF RELEASE NA 44 45 46 47 48 49 50																			

PERSONNEL EXPOSURES

NUMBER 13 0 0 0 7 8 9										TYPE Z 11 12										DESCRIPTION NA 13 14 15 16 17 18 19 20									
--------------------------	--	--	--	--	--	--	--	--	--	-----------------	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES

NUMBER 14 0 0 0 7 8 9										DESCRIPTION NA 11 12 13 14 15 16 17 18 19 20									
--------------------------	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--

OFFSITE CONSEQUENCES

15 NA 7 8 9																																																																															
-------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z 7 8 9										DESCRIPTION NA 11 12 13 14 15 16 17 18 19 20									
--------------------	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--

PUBLICITY

17 NA 7 8 9										8304070574 760604 PDR AD0CK 05000244 S PDR									
-------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

18 Corrective Action Report 1080 has been initiated for this event.																																																																															
---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

19 7 8 9																																																																															
----------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME: Thomas A. Meyer

PHONE: 716/546-2700, ext. 291-206

Licensee Event Report
Reportable Occurrence 50-244/76-16

Cause Description (cont'd.)

computer will be continued, and a Tech. Spec. change will be considered to eliminate further reports of this event when a suitable alternative is in effect.



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

June 4, 1976

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 76-16 (30-day report), Control Rod
position deviation channel
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-16, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)
Mr. William G. McDonald (3)

5824

COPY SENT REGION I