

DMB

UNION ELECTRIC COMPANY

1901 GRATIOT STREET
ST. LOUIS, MISSOURI

April 18, 1984

DONALD F. SCHNELL
VICE PRESIDENT

MAILING ADDRESS:
P. O. BOX 149
ST. LOUIS, MISSOURI 63166

Mr. James G. Keppler
Regional Administrator
USNRC Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

ULNRC-804

Dear Mr. Keppler:

AMENDMENT TO 10CFR50.55(e) REPORT U-72
PENETRATION SEAL INSTALLATION AND INSPECTION
CALLAWAY PLANT

Ref: ULNRC-786 April 4, 1984


On April 4, 1984, Union Electric submitted to the NRC Region III the reference final 10CFR50.55(e) report regarding silicone foam penetration seals. The report stated "Reinspection and any necessary repairs will be complete by April 22, 1984 on all silicone foam-filled wall and floor penetrations."

Subsequent review of the schedule and the work progress indicates that not all of the referenced seals will be completed by this date. Therefore, as required in the Callaway Plant Technical Specification, Limiting Condition for Operation, a fire watch will be established at the time of fuel load in accordance with the Action Statement of 3.7.11a as follows:

"With one or more of the above required fire barrier penetrations inoperable, within 1 hour establish a continuous fire watch on at least one side of the affected penetration, or verify the OPERABILITY of fire detectors on at least one side of the inoperable fire barrier and establish an hourly fire watch patrol."

These measures will ensure that the integrity of the fire protection program is maintained until any inoperable silicone foam penetration seals are restored to an operable status.

Very truly yours,


Donald F. Schnell

JJM/slz

cc: W. L. Forney, NRC Region III
Richard DeYoung, Director I&E
Missouri Public Service Commission
NRC Resident Inspection Callaway Plant (2)

8404270198 840418
PDR ADOCK 05000483
S PDR

APR 23 1984
FE 27
1/2