



July 11, 1974



Mr. John F. O'Leary, Director  
Directorate of Licensing  
Office of Regulation  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Mr. O'Leary:

FLORIDA POWER & LIGHT COMPANY  
DOCKET NO. 50-251  
TURKEY POINT UNIT NO. 4

The abnormal occurrence report for Turkey Point Unit No. 4 dated July 5, 1974 has an error in the sequential number assigned to this abnormal occurrence. The corrected abnormal occurrence report number should read:

ABNORMAL OCCURRENCE NO. 251-74-1  
JULY 5, 1974  
OCCURRENCE DATE: JUNE 27, 1974; JULY 1, 1974; JULY 2, 1974  
TURKEY POINT UNIT NO. 4  
BORON INJECTION TANK BORON CONCENTRATION  
BELOW LIMITING CONDITION FOR OPERATION

We regret any inconvenience caused by this error.

Very truly yours,

A. D. Schmidt  
Director of Power Resources

DWR/knw

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire