

western union

telegram

DEB916

KB105 K VEC054 (DE JLA065) IM PDF MORRIS ILL (AUG 6) 507P CDT
MR BOICE GRIER DIRECTOR US ATOMIC ENERGY COMMISSION
REGIONAL 3 COMPLIANCE=

799 ROOSEVELT RD GLEN ELLYN ILL 60137

THIS IS TO CONFIRM CONVERSATION WITH H DANCE, REGION THREE
COMPLIANCE, 0 AUG 6 1971, CONCERNING DRESDEN UNIT 2 HPCI
HPCI TURBINE FAILURE TO RE-SET. THE UNIT WAS OPERATING AT
400 MWE WHILE ROUTINE HPCI SURVEILLANCE WAS CONDUCTED AT
10PM ON AUG 5 1971. THE HPCI TURBINE FAILED TO RE-SET DUE
TO A CONTROL VALVE LIMIT SWITCH WHICH WAS OUT OF
ADJUSTMENT. THIS FAILURE WOULD HAVE PREVENTED THE TURBINE
STOP VALVE FROM OPENING HAD THE SYSTEM BEEN REQUIRED AND

IT THEREFORE REPORTED UNDER DPR-19 TECHNICAL SPECIFICATION
SECTION 6.6 REPAIRS WERE MADE AND A SUCCESSFUL HPCI RUN
WAS COMPLETED BY 3PM ON AUG 6 1971=

H K HOYT SUPERINTENDENT DRESDEN NUCLEAR POWER

STATION.==

181 JHK/staff 8/18/71

AUG 10 1971

PER OUR CY...

TELEPHONE *828 2660*
TELEPHONED TO *1952a*
TIME DELIVERED *med*
BY *med* TO BE *med*

8304080123 710810
PDR ADOCK 05000237
G PDR

MEMO ROUTE SLIP

Form AEC-93 (Rev. May 14, 1947)

See me about this.

For concurr

For action.

Note and return.

For signature.

For information.

TO (Name and unit)

J. Keppler
CO:HQ

INITIALS

DATE

REMARKS

TWX INCIDENT REPORT - DRESDEN 2 (50-237)

TO (Name and unit)

INITIALS

DATE

REMARKS

TO (Name and unit)

INITIALS

DATE

REMARKS

FROM (Name and unit)

Gaston Fiorelli *for*
CO:III

REMARKS

In accordance with PI 1000, attached is the original TWX
report dated 8-6-71 reporting the failure of the HPCI turbine
to re-set.

PHONE NO.

DATE

8-10-71

14670

Copy sent PDR

USE OTHER SIDE FOR ADDITIONAL REMARKS

U. S. GOVERNMENT PRINTING OFFICE: 1947 O-427007