



February 18, 1974



Mr. John F. O'Leary, Director  
 Directorate of Licensing  
 Office of Regulation  
 U.S. Atomic Energy Commission  
 Washington, D. C. 20545

Dear Mr. O'Leary:

FLORIDA POWER & LIGHT COMPANY  
 DOCKET NO. 50-250  
TURKEY POINT UNIT NO. 3

The abnormal occurrence report for Turkey Point Unit No. 3 dated February 15, 1974 has a typographical error in the sequential number assigned to this abnormal occurrence. The corrected abnormal occurrence report number should read:

ABNORMAL OCCURRENCE NO. 250-74-3  
 FEBRUARY 15, 1974  
 OCCURRENCE DATE: FEBRUARY 6, 1974  
FAILURE OF NO. B EMERGENCY DIESEL GENERATOR TO AUTO START

We regret any inconvenience caused by this error.

Very truly yours,

*A. D. Schmidt*  
 A. D. Schmidt  
 Director of Power Resources

VTC:df

cc: Mr. Norman C. Moseley, Director Region II  
 Directorate of Regulatory Operation  
 U.S. Atomic Energy Commission  
 Suite 818  
 230 Peachtree Street, N.W.  
 Atlanta, Georgia 30303

Jack R. Newman

8304080443 740218  
 PDR ADOCK 05000250  
 S PDR

COPY SENT REGION *II*

*1416*  
*50250*  
 HELPFUL BUILD FLORIDA