

December 16, 1974




Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Giambusso:

Re: Turkey Point Unit No. 3 - Docket No. 50-250
Inspection of Safety Related Hydraulic Pipe
Restraints that are Inaccessible During
Power Operation

On November 30, 1974, while the reactor was shutdown for refueling, an inspection of the Bergen-Paterson safety related hydraulic pipe restraints inaccessible during power operation was conducted. One restraint, out of fifty restraints which were inspected, exhibited a hydraulic fluid level below the minimum allowable level. This restraint was replaced with a spare unit.

Very truly yours,


Robert E. Uhrig
Vice President

REU:ncb

cc: Mr. Jack R. Newman
Mr. Norman C. Moseley

12795

8304110100 741024
PDR ADOCK 05000251
Q PDR

COPY SENT REGION 