



October 23, 1974

Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545




Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 3
DOCKET NO. 50-250
INSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS

Inspection of the safety related pipe restraints that are accessible during power operation was completed on October 21, 1974, in accordance with the continuing requirements of the Atomic Energy Commission Directorate of Licensing letter of November 8, 1973. All of the restraints were found to be in an operable condition. Hydraulic fluid was added to two restraints to bring their fluid level to the upper end of the allowable level band. The inspection included a total of 20 restraints and all are of the Bergen-Paterson design.

Very truly yours,


Robert E. Uhrig
Vice President

REU/HNP/cpc

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

8304110109 741024
PDR ADCK 05000251
G PDR

20-250
incident

11150

COPY SENT REGION