



June 4, 1974

rec'd 6-10-74
3:30 PM

Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 4
DOCKET NUMBER 50-251
REINSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS INACCESSIBLE
DURING POWER OPERATION

Reinspection of the subject piping restraints was completed on May 25, 1974, in accordance with the continuing requirements of the Directorate of Licensing letter of November 8, 1973. There were 50 restraints inspected. Thirty-four of these restraints are of the Bergen-Paterson design and 16 are of the Power Piping design. All of the restraints were found to be in satisfactory condition.

Very truly yours,

R. E. Uhrig
Vice President

REU/HNP/kmw

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

Handwritten notes: "Inventy", "ROB", "95-4", "50251"