



May 24, 1974

Mr. Angelo Giambusso  
Deputy Director for Reactor Projects  
Directorate of Licensing  
Office of Regulation  
U. S. Atomic Energy Commission  
Washington, D. C. 20545


Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 4  
DOCKET NO. 50-251  
INSPECTION OF SAFETY RELATED HYDRAULIC  
PIPE RESTRAINTS

Inspection of the safety related pipe restraints that are accessible during power operation was completed on May 13, 1974, in accordance with the continuing requirements of the Atomic Energy Commission Directorate of Licensing letter of November 8, 1973.

The inspection showed that all of the restraints were operable. However, two restraints located on the main steam piping showed evidence of excessive hydraulic fluid leakage. Although these restraints were operable, they were replaced with spare restraints due to the extent of the leak.

Very truly yours,

  
R. E. Uhrig  
Vice President

REU/DWR/kmw

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire

50-251  
R6B  
7-4

4941

8304110185 741024  
PDR ADOCK 05000251  
G PDR

COPY SENT REGION

HELPING BUILD FLORIDA