



January 29, 1974

Mr. Angelo Giambusso, Deputy Director
for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545



Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 3
DOCKET NUMBER 50-250
REINSPECTION OF SAFETY RELATED HYDRAULIC PIPE RESTRAINTS
ACCESSIBLE DURING POWER OPERATION

Reinspection of the accessible safety related piping restraints in accordance with the continuing requirements of the Directorate of Licensing, letter of November 8, 1973, was completed on January 18, 1974. There are 14 restraints which are in the above category and all are of the Bergen Paterson design. The inspection showed that all of the restraints were in satisfactory condition with no signs of hydraulic fluid leakage. As noted in our letter of January 11, 1974, all of these restraints have been rebuilt utilizing the recommended ethylene propylene seal material.

Very truly yours,

Robert E. Uhrig
Director of Nuclear Affairs

REU/HNP:paz

cc: Mr. Jack R. Newman

8304120034 741024
PDR ADDCK 05000251
Q PDR

COPY SENT REGION

864