

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: (10)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE (815) 942-2920 X526



Commonwealth Edison

Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

DMB

April 18, 1984

DJS Ltr. #84-393

James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #82-14/03X-2, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2(d), abnormal degradation of systems other than those specified in item B.1.e. above designed to contain radioactive material resulting from the fission process. This updated report changes future corrective actions from changing procedure DAP 2-8 to initiating a policy wherein maintenance departments receive a copy of related deviation reports.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/jmt

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

APR 25 1984

IE22
1/1

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT	YEAR	NO.
D - 12	-	3	-	82 - 20

PART 1		TITLE OF EVENT		OCCURRED	
		Discovery of Crack in Unit 3 Head Seal Leakoff Line		3/17/82	1700
				DATE	TIME
REASON FOR SUPPLEMENTAL REPORT					
A change to the corrective actions to prevent accidental loss of failed					
components that are related to deviation reports.					
PART 2					
ACCEPTANCE BY STATION REVIEW		<i>J. Brunner</i>		<i>J. A. Costa</i>	
DATE		4/18/84		4-19-84	
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION		<i>Douglas D. Witt</i>		4/25/84	
		STATION SUPERINTENDENT		DATE	