

Mr. Norman C. Moseley
Director of Region II
Directorate of Regulatory Operations
U. S. Atomic Energy Commission
230 Peachtree Street, N. W. Suite 818
Atlanta, Georgia 30303


Dear Mr. Moseley:

Re: Turkey Point Plant Unit No. 4
Docket No. 50-251

The reinspection of Unit No. 4 seismic restraints was completed November 5, 1973 in accordance with Regulatory Operations Bulletin No. 73-4. The 39 Bergen-Patterson restraints and 16 Power Piping Company restraints installed as replacements for Bergen-Patterson restraints during the previous outage were found to be in satisfactory condition.

Florida Power & Light Company (FPL) is continuing to seek reliable restraint materials. At this time various alternatives are being evaluated by FPL and its engineer-constructor. The Atomic Energy Commission will be advised of the results of this evaluation when it is completed.

Very truly yours,


Robert E. Uhrig
Director of Nuclear Affairs

REU:nch

cc: Mr. Jack R. Newman

RO

DEC 10 1973

Letter from Florida Power and Light Company, R. E. Uhrig,
dated December 5, 1973 - 50-251 - ROB 73-4

DISTRIBUTION:

H. D. Thornburg

RC:HQ (4)

Directorate of Licensing (4)

DR Central Files

PDR

Local PDR

NSIC

OIS, OR

U.S. ATOMIC ENERGY COMM
DIVISION OF COMPLIANCE

1973 DEC 12 PM 4 07

RECEIVED