



December 17, 1975
L-75-591

Director of Nuclear Reactor Regulation
Attn: Mr. Roger Boyd, Acting Director
Division of Reactor Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Boyd:

TURKEY POINT UNIT 4
DOCKET NO. 50-251
INSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS
LOCATED INSIDE CONTAINMENT



The subject inspection was completed on December 7, 1975
in accordance with the continuing requirements of the
Directorate of Licensing letter dated November 8, 1973.

All safety-related hydraulic pipe restraints located inside
containment were in satisfactory condition.

Very truly yours,

Robert E. Uhrig
Vice President

REU/MAS/jar

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

50-251

8304120237 751217
PDR ADOCK 05000251
Q PDR

14056