



November 10, 1975

L-75-547



Director of Nuclear Reactor Regulation  
Attention: Mr. Roger Boyd, Acting Director  
Division of Reactor Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Boyd:

TURKEY POINT UNIT 4  
DOCKET NO. 50-251  
INSPECTION OF SAFETY RELATED  
HYDRAULIC PIPE RESTRAINTS  
LOCATED OUTSIDE CONTAINMENT

TE FILE COPY

The subject inspection was completed on October 24, 1975, in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The inspection showed that all but one of fifteen restraints inspected were in satisfactory condition. One restraint located on a 30 inch Main Steam line had less than the minimum acceptable fluid level and was replaced with a spare unit.

Very truly yours,

Robert E. Uhrig  
Vice President

REU/MAS/cpc

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire

8304120251 751217  
PDR ADDCK 05000251  
G PDR

COPY SENT REGION

13159