



January 30, 1975  
L-75-62



Mr. Angelo Giambusso, Director  
Division of Reactor Licensing  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Giambusso:

Re: Turkey Point Unit No. 4 - Docket No. 50-251  
Safety Related Hydraulic Pipe Restraints  
Accessible During Power Operation

Inspection of the subject restraints in accordance with the continuing requirements of the Directorate of Licensing letter of November 8, 1973, was completed on January 15, 1975. Two of the fifteen restraints inspected had indicated fluid levels below the minimum allowable level and were replaced with spare units. These restraints were located on the main steam piping.

Very truly yours,

Robert E. Uhrig  
Vice President

REU:nch

cc: Mr. Norman C. Moseley  
Mr. Jack R. Newman