



January 17, 1975  
L-75-24



Mr. Angelo Giambusso  
Deputy Director for Reactor Projects  
Directorate of Licensing  
Office of Regulation  
U. S. Atomic Energy Commission  
Washington, D. C. 20545


Dear Mr. Giambusso:

Re: Turkey Point Unit No. 4  
Docket No. 50-251  
Inspection of Safety Related Hydraulic  
Pipe Restraints Inaccessible During  
Power Operation

On January 6, 1975, during an outage to repair a main condenser vacuum leak, an inspection of the subject restraints was performed in accordance with the continuing requirements of the Directorate of Licensing letter of November 8, 1973.

One out of 50 restraints had an indicated fluid level below the minimum acceptable level and was replaced with a spare unit. This restraint was located in the top of the pressurizer compartment on the Reactor Coolant System pressure relief piping.

Very truly yours,

  
Robert E. Uhrig  
Vice President

REU:HNP:ncb

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire

50-251  
inquiring

313

8304120293 751217  
PDR ADOCK 05000251  
PDR  
Q

COPY SENT REGION 