



November 21, 1974

Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Giambusso:

Re: Turkey Point Unit No. 4
Docket No. 50-251
Inspection of Accessible Hydraulic
Pipe Restraints

Inspection of the safety related hydraulic pipe restraints has been completed in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The inspection showed that two of the twenty restraints inspected had hydraulic fluid levels which were below the minimum allowable level. These were replaced with spare units.

Very truly yours,

Robert E. Uhrig
Robert E. Uhrig
Vice President

REU/HNP/cpc

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

50-251
ingulley

8304120311 751217
PDR ADOCK 05000251
G PDR

12226

COPY SENT REGION II

HELPING BUILD FLORIDA