



December 4, 1974



Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 3
DOCKET NO. 50-250
SAFETY RELATED HYDRAULIC
PIPE RESTRAINTS ACCESSIBLE
DURING POWER OPERATION

The inspection of the subject restraints in accordance with the continuing requirements of the Directorate of Licensing letter of November 8, 1973, was completed on November 21, 1974. Two of the twenty restraints inspected had indicated hydraulic fluid levels below the minimum allowable level and were replaced with spare units. These restraints were located on the 3A Residual Heat Removal Pump.

Very truly yours,

J. A. De Mastro

Robert E. Uhrig

REU/HNP/cpc

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

*50-250
inclosed*

12498