



November 1, 1974



Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Giambusso:

Re: Turkey Point Unit No. 4
Docket No. 50-251
Inspection of Safety Related
Hydraulic Piping Restraints

On October 27, 1974, Unit No. 4 was shutdown for repair of a steam generator sample line. During this shutdown, the fifty safety related hydraulic pipe restraints located inside the reactor containment were inspected in accordance with the continuing requirements of the Directorate of Licensing letter of November 8, 1973. The inspection showed that all of the restraints were in satisfactory condition. Hydraulic fluid was added to two restraints to bring their levels to the high end of the allowable range.

Very truly yours,


Robert E. Uhrig
Vice President

REU/HNP/cpc

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

8304120623 751217
PDR ADDCK 05000251
Q PDR

50-251
incident
11484
II
COPY SENT REGION
HELPING BUILD FLORIDA