

western union

Telegram

1975 JAN 24 PM 4:47

VEB247(1729)(2-038374E024)PD 01/24/75 1729

ICS IPMBNGZ CSF

8159424449 TDBN MORRIS IL 69 01-24 0529P EST

PMS JAMES G KEPPLER, REGIONAL DIRECTOR DIRECTORATE OF REGULATORY
OPERATION-REGION 3 US ATOMIC ENERGY COMMISSION, WUX

799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT: DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2

TELEPHONE NBR.

TELEPHONED TO

DATE DLR

ATTEMPTS TO DELIVER

OPR. NO.

BY

TIME

1/27

9:24 PM

1/25 8a 1216p

THIS WILL CONFIRM A CONVERSATION WITH MR JOHNSON OF YOUR OFFICE
AT 1540 HOURS THIS DATE CONCERNING FAILURE OF MO-2-22301-4 HIGH
PREASSURE COOLANT INJECTION STEAM VALVE IN THE MID POSITION
DURING HPCI LOGIC TEST 1-23-75. SYSTEM WAS NOT REQUIRED TO BE
OPERABLE AT THIS TIME. CAUSE OF FAILURE UNDER INVESTIGATION.

B B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION

8304140532 750407
PDR ADDCK 05000237
PDR


COMMONWEALTH EDISON CO RR NO 1 MORRIS IL 60450



Telegram

NNNN

JAN 29 1975



UNITED STATES
NUCLEAR REGULATORY COMMISSION
~~ATOMIC ENERGY COMMISSION~~
DIRECTORATE OF REGULATORY OPERATIONS
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

A. RO Inspection Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
RO Files

B. RO Inquiry Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ
DR Central Files
RO Files

C. Incident Notification From: Commonwealth Edison Co., Docket No. 50-237
(Licensee & Docket No. (or License No.))

Transmittal Date : FEB 28 1975

Distribution:
RO Chief, FS&EB
RO:HQ (4)
Licensing (4)
DR Central Files
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
RO Files

50-237
incident

TWX INCOMING

BETH
008

50-237



USAEC GTWN

WU INFOMASTER 1-038010C028 01/28/75
TLX WU TFC WSH
098
TWX 7108280476 USAEC GTWN

SPL098 WAB170(1745)(2-034177E026)PD 01/28/75 1745
ICS IPMBNGZ CSP
8159424449 TDBN MORRIS IL 85 01-28 0545P EST
PMS J F OLEARY, DIRECTOR, DIRECTORATE OF LICENSING, US ATOMIC
ENERGY COMMISSION, WUX
WASHINGTON DC 20545
SUBJECT: DPR-19, DRESDEN NUCLEAR POWER STATION UNIT 2.
THIS WILL CONFIRM A CONVERSATION WITH MR JOHNSON OF YOUR OFFICE
AT 0930 HOURS THIS DATE CONCERNING CRACKS FOUND OF CORE SPRAY
INJECTION LINES IN AREA OF LINE BETWEEN SAFE END AND INJECTION
LINE. CRACK THROUGH THE WALL WERE FOUND AT 8:00, 9 OCLOCK AND
12 OCLOCK IN N19A NOVEL AREA, AND AT 10 AND 1130 ON THE N19B
NOVEL AREA. INVESTIGATION INTO CAUSE OF FAILURE IS UNDER WAY
B B STEPHENSON, SUPERINTENDENT, DRESDEN NUCLEAR POWER STATION,
COMMONWEALTH EDISON CO, RRI MORRIS IL 60450

1904 EST

USAEC GTWN

1

976

PDE 1r

8103060534

TWX INCOMING

Telegram

1975 JAN 24 PM 4:47

VEB247(1729)(2-038374E024)PD 01/24/75 1729

ICS IPMBNGZ CSP

8159424449 TDBN MORRIS IL 69 01-24 0529P EST

PMS JAMES G KEPPLER, REGIONAL DIRECTOR DIRECTORATE OF REGULATORY
OPERATION-REGION 3 US ATOMIC ENERGY COMMISSION, WUX NO. _____ OPR. NO. _____

799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT: DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2.

TELEPHONE NO.

TELETYPE TO

TELETYPE TO

THIS WILL CONFIRM A CONVERSATION WITH MR JOHNSON OF YOUR OFFICE
AT 1540 HOURS THIS DATE CONCERNING FAILURE OF MO-2-22301-4 HIGH
PRESSURE COOLANT INJECTION STEAM VALVE IN THE MID POSITION
DURING HPCI LOGIC TEST 1-23-75. SYSTEM WAS NOT REQUIRED TO BE
OPERABLE AT THIS TIME. CAUSE OF FAILURE UNDER INVESTIGATION.

SF-1201 (10-75) B B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION

312-858-2660

ACK
1/27
4244
1/25 8-1216P