



Telegram

132P EDT OCT 5 70 PC133 SYD104

SY RHA203 BR RX PDF 3 EXTRA ROCHESTER NY 5 1255P EDT

R W KIRKMAN, DIRECTOR REGION 1 DIVN OF COMPLIANCE

USAEC 970 BROADST NEWARK NJER

THIS IS TO CONFIRM MY CONVERSATION AT 0940 THIS DATE WITH FLOYD CANTRELL IN REGARDS TO MALFUNCTION OF AN ENGINEERED SAFETY FEATURE AT GINNA STATION. ON SUNDAY OCT 4TH 1970 THE PLANT WAS IN A COLD SHUT DOWN CONDITION FOR SCHEDULED MAINTENANCE WORK. A 6" GAGE VALVE, #852B, WAS OPERATED AND IT ONLY OPENED HALF WAY. THIS VALVE HAS OPERATED SATISFACTORY DURING ITS LAST SURVEILLANCE TEST AND IT WAS ALSO OPERATED SATISFACTORY SEVERAL TIMES ON 10-3-70 AND 10-4-70. INVESTIGATION FOUND THE TROUBLE TO BE IN STEM NUT OF THE LIMITORQUE OPERATOR. THIS STEM NUT WILL BE REPLACED

CHARLES E PLATT SUPERINTENDENT GINNA STATION ROCHESTER GAS AND ELECTRIC CORP

SF-1201 (R5-69)

0940 4TH 1970 6" #852B WAS OPERATED 10-3-70 10-4-70 (102).

*Copy sent PDR, N52C + DTIE, OR  
10/8/70*

8304150580 701023  
PDR ADDCK 05000244  
S PDR

SF-1201 (R5-69)

