

28
Telegram

1055A EST JAN 19 72 PA131 MA097

M RHA087 SM PDF 4 EXTRA ROCHESTER NY 19 1000A EST

JAMES P O'REILLY DIRECTOR REGION 1 DIVN OF COMPLIANCE USAEC

970 BROAD ST NEWARK NJER

THIS IS TO CONFIRM MY CONVERSATION AT 0900 THIS DATE WITH FLOYD
CANTRELL OF YOUR OFFICE IN REGARDS TO AN ABNORMAL OCCURENCE
AT GINNA STATION AT 1145 ON JAN 18 1972 WHILE THE I AND C PERSONNEL
WERE CONDUCTING THE MONTHLY PT-5 SURVEILLANCE TEST A BISTABLE
ASSOCIATED WITH THE PRESSURIZER PRESSURE CHANNEL WAS FOUND
TO HAVE FAILED IN AN UNSAFE FAILURE MODE. FURTHER INVESTIGATION
FOUND THE PROBLEM TO BE IN A CAPACITOR. A NEW CAPACITOR WAS
INSTALLED AND THE BISTABLE WAS CHECKED OUT AND PUT BACK IN
SERVICE AT 1500 ON JAN 18 1972

CHARLES E PLATT SUPERINTENDENT OF GINNA STATION ROCHSTER
GAS AND ELECT CORP
(1019.

SF-1201 (RS-69)

2/4/72
RC
JW
MH
RM
m
8304200080 720119
PDR ADOCK 05000244
S PDR

Copy sent PDR