



July 8, 1975
L-75-245

Mr. George Lear, Chief
Operating Reactors Branch #3
Division of Reactor Licensing
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Dear Mr. Lear:

On March 10, 1975, Florida Power & Light Company submitted to you Supplement No. 63 to the Final Safety Analysis Report for Turkey Point Plant Units 3 and 4. The supplement contained the reevaluation of the ECCS in accordance with the Final Acceptance Criteria and the Order for Modification of Licenses for Turkey Point Units 3 and 4, dated December 27, 1974.

Enclosed is a copy of the report of Unusual Event No. 251-75-11 regarding the revised ECCS analysis for Turkey Point Unit No. 4. As discussed in the enclosed report, an error was made in the calculations performed by Westinghouse for our Turkey Point Unit No. 4. We have analyzed the situation and conclude that the margin that is available when operating Turkey Point Unit No. 4 in accordance with present Technical Specifications, which limit the maximum power to 2200 MWt, is sufficient to assure that there is no significant hazards consideration and that there is reasonable assurance that the health and safety of the public will not be endangered.

We are forwarding this report for your information and will furnish the results of our reanalysis to you when it becomes available.

Yours very truly,


Robert E. Uhrig
Vice President

REU:nch
Enclosure

cc: Jack R. Newman, Esq.

8304210174 750708
PDR ADDCK 05000251
S PDR

COPY SENT REGION 