



FLORIDA POWER &amp; LIGHT COMPANY

December 11, 1975

PRN-LI-75-11

Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 818  
Atlanta, Georgia 30303

Dear Mr. Moseley:

ABNORMAL OCCURRENCE 251-75-4  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: March 12, 1975

SUPPLEMENTARY REPORT NO. 3  
LATERAL RESTRAINTS FOR SPENT  
FUEL RACKS BROKEN

A. BACKGROUND

The finding in March, 1975, of several broken seismic restraint springs on the Unit 4 spent fuel racks led to the replacement of all Unit 4 springs and the inspection of the condition of Unit 3 springs. As reported in Supplementary Report No. 2 of August 5, 1975, damaged springs were also found on the Unit 3 spent fuel racks, and it was decided to replace all Unit 3 springs.

B. CORRECTIVE ACTION

All Unit 3 spent fuel rack seismic restraint springs have been replaced with new approved springs. Replacement work conducted from above the spent fuel pool using remotely operated tools was completed on October 30, 1975. All springs were changed and the new springs tensioned in accordance with procedures and engineering recommendations contained in Plant Change/Modification (PC/M) 75-20.


14030

8304210248 751211  
PDR ADOCK 05000251  
S PDR

Mr. Norman C. Moseley  
Page Two  
December 11, 1975

The completed PC/M package is available for review in the  
Turkey Point document files.

Very truly yours,



A. D. Schmidt  
Vice President  
Power Resources

MAS/pm

cc: Jack R. Newman, Esquire  
Director, Office of Inspection and Enforcement (40)  
Director, Office of Management Information and  
Program Control (3)