



Telegram

536P EST APR 27 72 DEB258

SSH246 DE CCB166 (SF 118CC228166) PD WU TSDEPT MOLI 0255P EST04/27/72

ZCZC 001 DG PD TDMS CORDOVA ILL 27 143P CFT
U S ATOMIC ENERGY COMM ATTN DUANE BOYD AND ED JORDAN
REGION 3 COMPLIANCE 799 ROOSEVELT RD GLEN ELLYN ILL

BT

REF QUAD CITIES NUCLEAR POWER STATION DPR-29 AND DPR-30 APPENDIX
A SECTION 6.6.A.1 - UNITS ONE AND TWO - THE WATER LEVEL IN THE
QNIT TWO REACTOR VESSEL WAS LOWERED FOR FINAL VISUAL INSPECTION
PRIOR TO HEAD INSTALLATION. TO PREVENT AUTO INITIATION OF THE
EMERGENCY DIESEL GENERATORS, JUMPERS WERE AUTHORIZED. IN ERROR
THE JUMPERS WERE PLACED ON UNIT ONE PANEL INSTEAD OF UNIT TWO
PANEL AT 700PM ON 4-26-72. AS A RESULT BOTH DIESEL GENERATORS
2 AND 1/2 STARTED AT 11:56PM ON 4-26-72 AND WERE LOADED ACCORDING
TO STATION PROCEDURES. AT 12:32AM ON RAWUAUW DIESEL GENERATOR

3/2-858-2660
TELEPHONE NO. 858-2660
TELEPHONED TO. dmh
TIME DELIVERED 559P
BY bmm TO BE MAIL

SF-1201 (R5-69)

MAY 1 1972



Telegram

#2 BECAME UNSTABLE AND WAS TRIPPED MANUALLY FROM THE CONTROL ROOM.
INVESTIGATION REVEALED A DAMAGED RECTIFIER IN THE CONTROL
SYSTEM. THE ERROR IN JUMPER PLACEMENT WAS CORRECTED AT 5AM ON
4-27-72. THIS ABNORMAL OCCURANCE IS REPORTED AS INCIDENT 2-72-3
COMMONWEALTH EDISON CO QUAD CITY NUCLEAR POWER STATION
B B STEPHENSON
NNNN(0300P EST)