



Telegram

1974 SEP 17 PH 3: 49

VEA247(1646)(1-035060A260)PD 09/17/74 1645

ICS IPMVEID MVN

04157 TDVE MORRIS IL 87 09-17 257P CDT

DATE OLD 8/18 TIME 8 56A
ATTEMPTS TO DELIVER. *mail*

PHS JAMES G KEPPLER RGNL DIR WUX DIRECTORATE REGULATORY OPERATIONS
RGN 3 US ATOMIC ENERGY COMM 799 ROOSEVELT ROAD
GLEN ELLYN IL 60137

SUBJECT DPR-19, DRESEN NUCLEAR POWER STATION UNIT 2 THIS WIDE
CONFIRM A CONVERSATION WITH F. MAURA OF YOUR OFFICE OF 1450
HOURS THIS DATE CONCERNING CRAK IN 2B REACTOR FEED PUMP MINIMUM
FLOW LINE AT THE LOCATION OF PREVIOUS REPAIRS. CRAK APPARENTLY
DEVELOPED 12 SEPTEMBER 74 AT 1500 HOURS BUT WAS NOT LOCATED AND
AND REPAIRED TILL SATURDAY 14 SEPTEMBER 74. DELAY IN REPORTING
CAUSED BY PRE-OCCUPATION WITH PROBLEMS WITH REACTOR
RECIRCULATION PIPING PREVIOUSLY REPORTED

B B STEPHENSON SUPERINTENDENT

DRESEN NUCLEAR POWER STATION

8305190549 740920
PDR ADDCK 05000237
PDR



Telegram

COMMONWEALTH EDISON CO
RR 1 MORRISON ILLINOIS 60450

NNNN

10142EB 11 PM 3-20

SEP 23 1974