

James G. Keppier, Regional Director  
Directorate of Regulatory Operations  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Televised Date 7-22-75  
GE                       
DC 11:14 A.M.  
By                     

cc:

Bernard C. Rusche, Director  
Directorate of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

SUBJECT: DPR- 15, Dresden Nuclear Power Station, Unit 3.

50-249

This will confirm a conversation with Mr P Johnson of  
your office at 0830 hrs this date concerning LOCATION OF TACK  
TACK WELDS ON JET pump RESTRAINER CLAMP BOLT KEEPERS  
DURING TV CAMERA EXAMINATION OF UNIT 3 JET pumps  
#6 AND #17. STRUCTURAL INTEGRITY OF THE JET pumps  
WERE FOUND SATISFACTORY AND NO PARTS WERE BROKEN  
LOOSE FROM THE RETAINER. ONLY ONE OF THE TWO  
CLAMP BOLT KEEPERS ON EACH JET pump WERE AFFECTED.  
REPAIR WILL CONSIST OF UNDERWATER TACK WELDING  
OF THE KEEPERS IN PLACE FOLLOWING TORQUE MEASUREMENTS  
OF THE CLAMP BOLTS IS FOUND SATISFACTORY.

8306090109 750731  
PDR ADOCK 05000249  
S PDR

\*\*\*\*\*  
To Call:

GE - 5-858-2660x16 (auto) - on 6  
DC - 9-1-301-492-7617 (auto)  
WU - 815-942-4449/4321

Station Dist: Originator (copy)

B. B. Stephenson, Superintendent  
Dresden Nuclear Power Station  
Commonwealth Edison Company  
R.R. 01  
Morris, IL 60450