



**Commonwealth Edison**  
Quad-Cities Nuclear Power Station  
Post Office Box 216  
Cordova, Illinois 61242  
Telephone 309/654-2241

IE FILE COPY

NJK-76-309

August 20, 1976



J. Keppler, Regional Director  
Office of Inspection and Enforcement  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137


Reference: Quad-Cities Nuclear Power Station  
Docket No. 50-254, DPR-29, Unit 1  
Appendix A, Sections 4.5.B.2, 6.6.B.2.c

Enclosed please find Reportable Occurrence Report No. 50-254/76-22  
for Quad-Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements  
of Technical Specification 6.6.B.2.


Very truly yours,

COMMONWEALTH EDISON COMPANY  
QUAD-CITIES NUCLEAR POWER STATION

  
N. J. Kalivianakis  
Station Superintendent

NJK/TPJ/lk

cc: G. A. Abrell

COPY SENT REGION 

5800

8306100296 760820  
PDR ADOCK 05000254  
S PDR

AUG 23 1976

**LICENSEE EVENT REPORT**

CONTROL BLOCK: 

--	--	--	--	--	--

  
                    1                                6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER								LICENSE TYPE					EVENT TYPE									
0	1		I	L	Q	A	D	I		0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1		0	3
7	8	9																		26						31	32	

01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE						REPORT DATE					
7	8	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80		
				L	L	0	5	0	-	0	2	5	4	0	7	2	3	7	6	0	8	2	0	7	6		

[illegible]

02 While returning the 1A RHR Service Water Pump to service it was discovered that the  
operability testing on the containment cooling loop required prior to removing the  
pump from service was performed on the wrong unit. Subsequent testing after discovery  
of the error showed that all components of both containment cooling loops were  
operable during the time the pump was out of service. This is the first occurrence

SYSTEM CODE		CAUSE CODE	COMPONENT CODE				COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
07	C F	A	P	U	M	P	X	X	N	I	0	7	5	N	
7	8 9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

## CAUSE DESCRIPTION

08	7	8	9	(Proximate Cause-Personnel Error) The supervisor on duty at the time the surveillance	80
09	7	8	9	was performed handed it to the wrong unit operator resulting in the tests being	80
10	7	8	9	performed on the wrong unit.	80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	8	3	NA		B	Testing after returning to service		
7	8	9	10	11	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED      CONTENT OF RELEASE      AMOUNT OF ACTIVITY      LOCATION OF RELEASE

1 2      Z      NA      NA

7 8      9 10 11      44      45 80

## PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	000	Z	NA	

## PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	NA

### OFFSITE CONSEQUENCES

1	5	NA	
7	8	9	80

## LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	6	Z	NA

## PUBLICITY

17	1A	80
----	----	----

### ADDITIONAL FACTORS

18 (EVENT DESCRIPTION CONT'D) of this type at Quad-Cities Station. (RO 50-254/76-22)

19 89 80

NAME: Thomas P. Joyce

PHONE: 309-654-2241 EXT. 247