

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

SHIELDS L. DALTROFF
VICE PRESIDENT
ELECTRIC PRODUCTION

(215) 841-5001

April 30, 1984

Docket No. 50-277

Dr. Thomas E. Murley
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

SUBJECT: I.E. Bulletin 80-07

Dear Dr. Murley:


The purpose of this letter is to provide an update regarding the issue of Jet Pump Beam Cracking with respect to Peach Bottom Unit 2.

It is our current plan to replace all of the jet pump beams with beams having improved heat treatment and 25 Kip preload during the upcoming outage scheduled to start April 27, 1984.

Subsequent to this replacement, it is requested that the inspection requirement of Bulletin 80-07 be suspended. Information provided by GE, contained in NEDE-24362-1 dated December, 1981, indicates that beams receiving the improved heat treatment and installed with a 25 Kip preload should not experience cracking during the remaining lifetime of the unit.

Should you have any further questions, do not hesitate to contact us.

Very truly yours,



cc. A. R. Blough, Site Inspector

8405210245 840430
PDR ADOCK 05000277
Q PDR

1/0

12 11