

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET NUMBER (2)
Washington Nuclear Project - Unit 2	0 5 0 0 0 3 9 7 1 GF 0 2

TITLE (4)

Loose Parts Detection Channel-6 Failure

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					DOCKET NUMBER(S)											
0	4	1	1	8	4	8	4	—	0	3	7	—	0	0	0	5	1	8	8	4	0 5 0 0 0				
																		0 5 0 0 0							

OPERATING MODE (9)		2	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following): (11)			
POWER LEVEL (10)	0.01		20.402(b)	20.405(c)	50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
			20.405(a)(1)(i)	50.38(c)(1)	50.73(e)(2)(v)	<input type="checkbox"/> 73.71(c)
			20.405(a)(1)(ii)	50.38(c)(2)	50.73(a)(2)(vii)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 365A)
			20.405(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(viii)(A)	Special Report
			20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)	
	20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(x)			

L.D. Kassakatis, Plant Compliance Engineer		5101931771-12151011
--------------------------------------------	--	---------------------

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	
A				N							

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
YES (), complete EXPECTED SUBMISSION DATE)	Y NO				

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)

During Initial Plant Heatup the piping in the Primary Containment was being inspected for movement and Loose Parts Detector Channel-6 was damaged. The damage occurred when an attempt to remove insulation was made prior to removing the detector. This detector monitors the A-Recirculation Pump (RRC-P-1A) Suction.

The cause of the malfunction has been determined to be either the detector or the cable or both.

Replacement was planned during an outage which was to occur on 5-1-84; however, plant testing has postponed the outage.

We have also experienced difficulty in obtaining a new detector and the present delivery date is late May.

The Plant Outage is presently scheduled for 5-21-84 and includes plans to restore Channel-6 to operable status.

8405230254 840518
PDR ADCK 05000397
S PDR

IF 22

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Washington Nuclear Project - Unit 2	0 5 0 0 0 3 9 7 8 4	—	0 3 7	—	0 0 0	2 OF 0 2

TEXT (If more space is required, use additional NRC Form 356A's) (17)

- (a) Power Level 1%
- (b) Plant Mode - 2
- (c) During Initial Power Operations

During Initial Plant Heatup the piping in the Primary Containment was being inspected for movement and Loose Parts Detector Channel-6 was damaged. The damage occurred when an attempt to remove insulation was made prior to removing the detector. This detector monitors the A-Recirculation Pump (RRC-P-1A) Suction.

The cause of the malfunction has been determined to be either the detector or the cable or both.

Replacement was planned during an outage which was to occur on 5-1-84; however, plant testing has postponed the outage.

We have also experienced difficulty in obtaining a new detector and the present delivery date is late May.

The Plant Outage is presently scheduled for 5-21-84 and includes plans to restore Channel-6 to operable status.

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397
May 18, 1984


Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: NUCLEAR PROJECT NO. 2
LICENSEE EVENT REPORT NO. 84-037

Dear Sir:

Transmitted herewith is Licensee Event Report No. 84-037 for WNP-2 Plant. This is a Special Report submitted pursuant to Technical Specification 6.9.2 and 3.3.7.10.

Very truly yours,


J. D. Martin (M/D 927M)
WNP-2 Plant Manager

JDM:mm

Enclosure:
Licensee Event Report No. 84-037

cc: Mr. John B. Martin, Administrator
Region V, Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
1450 Maria Lane
Walnut Creek California 94596
Mr. A. D. Toth, NRC Resident Inspector (901A)
Ms. Dottie Sherman
American Nuclear Insurers
The Exchange Suite 245
270 Farmington Ave.
Farmington, CT 06032

IE22
1/1