



Commonwealth Edison
Quad-Cities Nuclear Power Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-75-506

Telecopy: Region III, Attention: Mr. C. Feierabend

October 14, 1975

J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2
Docket No. 50-265, DPR-30
Appendix A, Sections 1.0.A.5, 6.6.B.1.a

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

With Unit 2 in the Cold Shutdown Condition, weld examinations were conducted on the reactor recirculation discharge bypass lines. On October 14, 1975, a crack indication was confirmed on the "B" Loop at the junction of the bypass line with the 28 inch discharge header on the downstream side of the bypass valve. The crack indication is in the heat affected zone on the pipe side of the pipe-to-weldolet weld. Plans concerning the repairs to be made are incomplete at this time.

This occurrence was discussed by telephone with Mr. Knop of your office on October 13, 1975, and further with Mr. Feierabend on October 14, 1975. Further information will be provided by Abnormal Occurrence Report AO 50-265/75-38 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
Station Superintendent

NJK/REQ/vmb

cc: Office of Nuclear Reactor Regulation
G. A. Abrell

8306170239 751014
PDR ADDCK 05000265
S PDR



22403