

## LICENSEE EVENT REPORT

CONTROL BLOCK

1						6
---	--	--	--	--	--	---

(PLEASE PRINT ALL REQUIRED INFORMATION)

01 ALBRF1 00-00000-00 41111 03

7 8 9 14 15 25 26 30 31 32

01 CONT CATEGORY REPORT TYPE REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

7 8 57 58 59 60 61 68 69 74 75 80

[illegible]

02	A raw service water tank level switch became stuck and prevented the start of a raw	80
03	service water pump. This caused the tank to be drained below the minimum level	80
04	specified in the Technical Specifications, and required the starting of a fire pump.	80
05	( )	80
06		80

SYSTEM CAUSE

PRIME

07 7 8 9 10 11 12 13 14 15 16 17 43 44 45 46 47 48

SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

A B E I N S T R U L M 2 3 5 N

## CAUSE DESCRIPTION

08	A Mercoird-type 251-CMP-S13Y-S1D4 level switch became stuck due to slight shifting	
7	8	9
09	of the operating mechanism. The mechanism was adjusted to prevent binding and the	80
7	8	9
10	switch was returned to service.	80
7	8	9

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	1	0	0	0	N/A		A	Alarms received in control room		
7	8	9	10	11	12	13	14	15	16	17

ACTIVITY RELEASED: 12  
CONTENT OF RELEASE: 2  
AMOUNT OF ACTIVITY: N/A  
LOCATION OF RELEASE: N/A

## PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	3	N/A

## PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

## OFFSITE CONSEQUENCES

15 N/A

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	8	N/A

## PUBLICITY

17	1	N/A
----	---	-----

### ADDITIONAL FACTORS

[illegible]

8306240292 760811  
PDR ADOCK 05000259  
S PDR

80

NAME: \_\_\_\_\_ PHONE: \_\_\_\_\_



259/76-12

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

IE FILE COPY

August 11, 1976

COPY SENT REGION *A*



Mr. Norman C. Moseley, Director  
U.S. Nuclear Regulatory Commission  
Region II  
230 Peachtree Street, NW., 8th Floor  
Atlanta, Georgia 30303

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 -  
DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE  
OCCURRENCE REPORT BPRO-50-259/7612W

The enclosed report is to provide details concerning a raw service water tank level switch which became stuck and prevented the start of a raw service water pump and is submitted in accordance with Appendix E to Regulatory Guide 1.16, Revision 4, August 1975. This event occurred on Browns Ferry Nuclear Plant unit 1.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox  
Director of Power Production

Enclosure (3)

CC (Enclosure):

Director (3)

Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director (40)/

Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

IE FILE COPY

COPY SENT REGION *A*

8252