

NJK-75-76

Telecopy: Region III, Attention: Mr. C. Reierabend

February 19, 1975

J. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2
Docket No. 50-265, LPR-30
Appendix A, Sections 1.0.A.4, 6.6.B.1.a

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

With Unit 2 in the cold shutdown condition for the current refueling outage, jet pump inspections revealed the following discrepancies:

1. Jet Pump #7 - missing a beam bolt retainer and cap screw.
2. Jet Pump #8 - missing a beam bolt retainer and cap screw.
3. Jet Pump #18 - missing the restrainer gate adjusting screw on the shroud side.
4. A piece of wire was observed loose in the annulus area.

The missing beam bolt retainers and cap screws should not affect the operation of jet pumps 7 and 8. The missing restrainer gate adjusting screw should not prevent jet pump 18 from being adequately secured since the beam bolt was properly torqued and intact.

An attempt will be made to retrieve all missing parts from the reactor vessel. Plans are being developed to install a new adjusting screw on the jet pump 18 restrainer gate.

This occurrence was discussed by telephone with Mr. Knop of your office on February 18, 1975. Further information will be provided by Abnormal Occurrence Report AO-50-265/75-8 which will be submitted within 10 days of this occurrence.

Very truly yours,
COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
N. J. Kalivianakis
Station Superintendent
NJK/SRI/saa

8306280108 750729
PDR ADOCK 05000265
S PDR

cc: Directorate of Licensing J. S. Abel