

LICENSEE EVENT REPORT

(PLEASE PRINT ALL REQUIRED INFORMATION)

CONTROL BLOCK: 																																																	
LICENSEE NAME: A L B R F 2										LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0										LICENSE TYPE: 4 1 1 1 1					EVENT TYPE: 0 3																								
CATEGORY: CONT										REPORT TYPE: L					REPORT SOURCE: L					DOCKET NUMBER: 0 5 0 - 0 2 6 0										EVENT DATE: 1 0 1 2 7 6										REPORT DATE: 									

EVENT DESCRIPTION

Control room annunciator 2-XA-55-8E failed. This annunciator is for smoke and heat																																																																															
alarms in the fire protection system.																																																																															

SYSTEM CODE: A B										CAUSE CODE: E										COMPONENT CODE: A N N U N d										PRIME COMPONENT SUPPLIER: L										COMPONENT MANUFACTURER: L 2 9 5										VIOLATION: N									
--	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

CAUSE DESCRIPTION

The power supply card failed, Lundell Controls part number 310948 in the Statalarm																																																																															
annunciator. (BFRO-50-260/7614)																																																																															

FACILITY STATUS: B										% POWER: 0 5 9										OTHER STATUS: N/A										METHOD OF DISCOVERY: A										DISCOVERY DESCRIPTION: N/A									
FORM OF ACTIVITY RELEASED: 2										CONTENT OF RELEASE: 2										AMOUNT OF ACTIVITY: N/A										LOCATION OF RELEASE: N/A																			

PERSONNEL EXPOSURES

NUMBER: 0 0 0										TYPE: 2										DESCRIPTION: N/A									
---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES

NUMBER: 0 0 0										DESCRIPTION: N/A									
---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

OFFSITE CONSEQUENCES

N/A																																																																															
-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE: 2										DESCRIPTION: N/A									
---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

PUBLICITY

N/A																																																																															
-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

Replaced power supply card and returned annunciator to normal																																																																															

NAME _____

PHONE _____



TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

November 10, 1976

Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE
OCCURRENCE REPORT BFRO-50-260/7614

The enclosed report is to provide details concerning control room
annunciator 2-XA-55-8E that failed. This report is submitted in
accordance with Browns Ferry Technical Specifications Section 6.
This event occurred on Browns Ferry Nuclear Plant unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)

CC (Enclosure):

Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



11661