



Commonwealth Edison
Quad-Cities Generating Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-75-64

Telecopy: Region III, Attention: Mr. C. Feierabend

February 11, 1975



J. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2
Docket No. 50-265, DPR-30
Appendix A, Sections 1.0.A.2, 3.2.A, Table 3.2.1, 6.6.B.1.a

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

With Unit 2 in the cold shutdown condition for the current refueling outage, routine quarterly surveillance on high pressure coolant injection system flow switches revealed that flow switch 2-2352 would not trip at any differential pressure. This inoperable flow switch caused a violation of the operability requirements of Table 3.2.1 of Technical Specifications.

The flow switch linkage which was binding, was adjusted and the flow switch was recalibrated.

This occurrence was discussed by telephone with Mr. Knop of your office on February 10, 1975. Further information will be provided by Abnormal Occurrence Report A0 50-265/75-7 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
Station Superintendent

8306290011 750218
PDR ADOCK 05000265
S PDR

NJK/IK

1778

cc: Directorate of Licensing
J. S. Abel