



Telegram

73P ED1 JUN 7 72 AB147 KA337

K CMA448 CS PDF 2 EXTRA TDCM HARTSVILLE SOCAR 7 422P EDT  
JOHN G DAVIS, DLR

DIR AEC DIVN OF COMPLIANCE DIVN 2 230 PEACHTREE ST ATLA  
IN ACCORDANCE WITH SECTION 6.6.1.C TECHNICAL SPECIFICATION  
THE FOLLOWING ABNORMAL OCCURANCES IS REPORTED ON A ROUTINE  
CHECK OF THE CONTAINMENT SPRAY PUMP A PUMP WAS FOUND TO BE  
BINDING. THIS PUMP IS BEING DISASSEMBLED FOR REPAIRS AT THIS  
TIME THE THE REACTG WILL NOT BE TAKENNCRITICAL UNTIL THE PUMP  
IS OPERABLETHIS OCCURANCE WAS REPORTED TMMR DON KIRKPATRICK  
IN PERSON ON 6-7-72

G P BEATTY JR PLANT SUPT H B ROBINSON SEG PLANT

6.6.1.C 6-7-72

(737).

SF-1201. (R5-69)

8307250707 720616  
PDR ADDCK 05000261  
S PDR