

1974 JUN 10 PM 7 29

U.S. ATOMIC ENERGY COMM.
T W X UNIT

USAEC HQS GTWN

WU WSH

OTLXA214 WAG225(1601)(1-F29896C161002)PD 06/10/74 1559

ICS 1PMVEIC MVN

03210 TDVE MORRIS ILL 123 0-10 147P CDT

PMS MR J F O'LEARY

DIRECTOR DIRECTORATE OF LICENING

WUX US ATOMIC ENERGY COMMISSION

WASHDC 20545

50-249

SUBJECT DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3
THIS WILL CONFIRM A CONVERSATION WITH F MAURA OF
YOUR OFFICE AT 1325 HOURS THIS DATE CONCERNING A FAILURE
OF A THREE QUARTER INCH NIPPLE ON REACTOR FEED PUMP DISPATCH
LINE 3-3201-24 A THROUGH WALL CRACK APPROXIMATELY ONE QUARTER
INCH IN LENGTH DEVELOPED DURING OPERATION ON THREE QUARTER
INCH NIPPLE BETWEEN MANUAL DRAIN VALVE 3-3201-500 AND 501
AND THE COMMON FEED PUMP DISCHARGE HEADER 3-3201-24 INCH
PREPARATION FOR REPAIR ARE CURRENTLY UNDER WAY ADDITIONAL
DETAILS AND CORRECTIVE ACTION WILL BE SUPPLIED IN THE FORM OF
A TEN DAY LETTER IN ACCORDANCE WITH SECTION 6.6.B.1.A OF
THE TECHNICAL SPECIFICATION

B B STEPHENSON

SUPERINTENDENT

DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON COMPANY

? R I

MORRIS ILLINOIS 60450



NNNN

8310190140 740618
PDR ADOCK 05000249
S PDR

COPY SENT REGION

5211