

● LICENSEE EVENT REPORT ●

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSE NAME
01 097514

LICENSE NUMBER
00-0000-0000 411420

CATEGORY
01 CONT M I

REPORT TYPE
7

REPORT SOURCE
L

DOCKET NUMBER
050-0267

EVENT DATE
072678

DATE OF COPY
000000

EVENT	DESCRIPTION
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

Operator was returning recirculator to service when
discharge valve was opened. IC circulator tripped,
was restarted, and returned to service.

CAUSE DESCRIPTION

08 Opening discharge valve caused buffer differential
7 8 9 pressure to exceed trip point. No resolution yet.
09
7 8 9
10 determined.
7 8 9

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	8	0	1	1			A		N/A	
7	8	9	10	12	13		44	45	46	80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
12	3	3	11	N/A	44	N/A	80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	3	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION			
1	4	0	0	0	11	12	80
7	8	9					

OFFSITE CONSEQUENCES

15 | N/A

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION	
1	5	1	N/A	
7	8	9	8311110104 770713	

PUBLICITY

17 N/A S PDR 7 8 9 80

ADDITIONAL FACTORS

13 N/A

19

NAME W. L. Campbell U. W. Hilliard, Jr. PHONE 703-725-0250