

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.  
VICE PRESIDENT  
NUCLEAR OPERATIONS

34 MAR 5 P/2  
February 29, 1984

Mr. James P. O'Reilly  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region II, Suite 2900  
101 Marietta Street, N.W.  
Atlanta, Georgia 30303


SUBJECT: Virgil C. Summer Nuclear Station  
Docket No. 50/395  
Operating License No. NPF-12  
Special Report (SPR 84-002)

Dear Sir:

Please find attached a Special Report for the Virgil C. Summer Nuclear Station. This Report is required by Technical Specification 6.9.2 as a result of entry into Action Statement (a) of Technical Specification 3.7.10, "Fire Rated Assemblies," on January 31, 1984.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

RBJ:OWD/dwf/gj  
Attachment

cc: V. C. Summer	C. L. Ligon (NSRC)
T. C. Nichols, Jr./O. W. Dixon, Jr.	K. E. Nodland
E. H. Crews, Jr.	R. A. Stough
E. C. Roberts	G. Percival
W. A. Williams, Jr.	C. W. Hehl
D. A. Nauman	J. B. Knotts, Jr.
Group Managers	I&E Washington
O. S. Bradham	Document Management
C. A. Price	Branch
D. A. Lavigne	INPO Records Center
J. F. Heilman	NPCF
	File

8403070337 840229  
PDR ADDCK 05000395  
S PDR

OFFICIAL COPY

JEZ

1/0

Mr. James P. O'Reilly  
SPR 84-002  
Page Two  
February 29, 1984

EVENT DESCRIPTION

On January 31, 1984, the fire rated wall in Room 63-15, Control Building, 463' Elevation, was degraded. A hole of approximately two (2) inches in diameter occurred when a chair was pushed against the wall. Because of a personnel error, the damaged area was not repaired until February 16, 1984.

The subject room is utilized by shift personnel and also protected by an ionization detector.