

Veeco

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station
P.O. Box 315
Surry, Virginia 23883

October 1, 1975

Director of Regulatory Operations
230 Peachtree Street, N. W.
Suite 818
Atlanta, Georgia 30303

This is to inform you by telecopy of an Abnormal Occurrence that was noted on September 28, 1975 at Surry Nuclear Power Station.

While Refueling Performance Test 18.2 was being performed on one train, the safety injection master relay failed to latch, violating Technical Specification 3.3. The redundant train as well as practically all outputs of the effected train operated correctly.

E. M. Sweeney, Jr.
E. M. Sweeney, Jr.
Manager *by 11/1*

8403120284 751001
PDR ADOCK 05000280
S PDR

54-080
54-081